

Waterwatch Data Record Sheet

Monitor

			The second secon
Date and time:	18/8/17	11:00 am	Site Code: M00023
Waterway and lo	ocation:		
		and moorabo	ol R, Shaps Br
ari Bil I		1	
Site Risk Assessn	nent completed — ye	s / no	

Are there any incidents or near misses to report? – (if yes, please let Deirdre or Warren know)

Parameter	Results
рН	
(pH units)	7.5 PH
Electrical conductivity	1183 US
(record as μS/cm)	(Write units displayed on meter. If needed multiply by 1,000 to convert mS to μ S)
Turbidity	
(NTUs)	< 10
Reactive phosphorus	
(mgP/I)	0.015

Photos of monitoring site taken upstr	eam, across stream and downstream?
These photos, with a heading to identify t	the sitecode, can be sent as an MMS to 0418145818 or emailed to
deirdre.murphy@ccma.vic.gov.au.	
Additional observations eg what birds	s, plants, frogs are present?
birds	
Record amount of litter	Record amount of illegal dumping
Rating 1 to 5	Rating 1 to 5
	Do you need to take a photo and report to EPA?