

Waterwatch

Water Quality Data Form

Site: Old pipe Bridge
Monitoring group: Plenty River
Persons monitoring: Alice, Pama, Daman, secun, carley

Date: 23.03.26
Time: 9.15am

Circumstantial Hazard or Additional Risks

Hazard: Slippery ground
Risk: slips, trips, falls
Risk Control Measures: good shoes

Safety Check

Has anything changed at your site recently?
Are there extreme weather conditions?
Any animals or insects nearby that pose a risk?



Parameter		Reading
Ammonium		mg / L
Dissolved Oxygen	(Use data portal to auto calculate % saturation)	8 mg / L
Water Temperature		18.9 °C
Air Temperature		17.6 °C
pH	☒ Calibrated	7.3 (7.5) Unit
Electroconductivity	☒ Calibrated	536 (522) µS / cm
Phosphate	(for colorimeter use conversion on data portal, or divide by 0.326 to calculate PO4-P mg/L)	0.02 mg / L
Turbidity		19 NTU
Nitrate		0 mg / L

Comments: New kit in use from this testing for Ammonium. ammonium was tested 2 times & conflicting results found.



melbournewater.com.au/waterwatch



Waterwatch Observations

Weather

Condition:

☒ Sunny
☐ Raining

☐ Cloudy
☐ Windy

☐ Overcast

Rainfall

Last Rainfall:

☐ More than a week ago

☒ During the last week

☐ During the last 24 hours

☐ Raining now

Amount of rain (mm): 14mm

Water Flow

Flow Indicator (ML/Day): 11.2 ml/day

Estimate of flow:

☐ Flood / overbank

☐ Bankfull

☐ High

☒ Medium

☐ Low

Water Appearance

☒ Clear

☐ Scummy

☐ Smelly

☐ Foamy / frothy

☐ Stained brown

☐ Muddy

☐ Milky

☐ Oily

☐ Stained green

Other:

Stream Depth:

☒ 0-50cm

☐ 51cm - 99cm

☐ 1m - 2m

☐ Other

Stream Width:

☐ <2m

☐ 2 - 5m

☐ >5m

☐ Other

Drains

Is water flowing from drain? ☐

Colour

Odour

Litter Pollutants

☐ Bottles

☐ Car bodies

☐ Oil

☐ Paper

☐ Plastic

☐ Waxed cardboard

☐ Cans

☐ Clothing

☐ Packets

☐ Petrol / diesel

☐ Polystyrene

Other:



melbournewater.com.au/waterwatch



**Melbourne
Water**

Enhancing Life and Liveability