Monitor



Waterwatch Data Record Sheet

Date and time:	:0:20		Site Code:
18-08-17	10:30 a	~	CO-AM5025
Waterway and location:			
ARMSTRONG CREEK SITE 2 Waratily			
Site Risk Assessment completed - yes/ no			
Are there any incidents or near misses to report? (if yes, please let Deirdre or Warren know)			
Parameter	Results		
рН	_		
(pH units)	7-5		
Electrical conductivity	12,58		
(record as μS/cm)	(Write units displayed on meter. If needed multiply by 1,000 to convert mS to μS)		
Turbidity	<20		
(NTUs)			
Reactive phosphorus			
(mgP/I)	0.03		
Photos of monitoring site taken upstream, across stream and downstream?			
These photos, with a heading to identify the sitecode, can be sent as an MMS to 0418145818 or emailed to deirdre.murphy@ccma.vic.gov.au .			
Additional observations eg what birds, plants, frogs are present?			
Ducks, moorfowel, wagtails			
Record amount of litter		Record amount of illegal dumping	
Rating 1 to 5 MA 3		Rating 1 to 5	
		Do you need to take a photo and report to EPA?	