



**Waterwatch Data Record Sheet**

Monitor  
P Syme

Date and time: 18/04/17	11:20 am	Site Code: CO_BA2125
Waterway and location: MID BARWON 2ND SITE Fyans Park Boat Ramp.		
Site Risk Assessment completed – yes / <u>no</u>		
Are there any incidents or near misses to report? – (if yes, please let Deirdre or Warren know)		

Parameter	Results
pH (pH units)	7.5
Electrical conductivity (record as $\mu\text{S}/\text{cm}$ )	1323 (Write units displayed on meter. If needed multiply by 1,000 to convert mS to $\mu\text{S}$ )
Turbidity (NTUs)	< 20 NTU
Reactive phosphorus (mgP/l)	0.06

Photos of monitoring site taken upstream, across stream and downstream?  These photos, with a heading to identify the sitecode, can be sent as an MMS to 0418145818 or emailed to <a href="mailto:deirdre.murphy@ccma.vic.gov.au">deirdre.murphy@ccma.vic.gov.au</a> .	
Additional observations eg what birds, plants, frogs are present? MAGPIES, CAN HEAR CANT HEAR FROGS	
Record amount of litter Rating 1 to 5 ZERO VISIBLE LITTER	Record amount of illegal dumping Rating 1 to 5 NO DUMPING Do you need to take a photo and report to EPA?