WATERWATCH Corangamite

Waterwatch Data Record Sheet

Communities Caring for Catchments

Date and time:	17 10:30an		Site Code: CO_MOC045
001/			
Waterway and location:			
Moorabool River reserve			
Site Risk Assessment completed – ves/ no			
Are there any incidents or near misses to report? – (if yes, please let Deirdre or Warren know)			
Parameter	Results		
		·	
рН			
(pH units)	7.5		
(pri units)			
Electrical conductivity	1696 MS		
(record as μS/cm)	(Write units displayed on meter. If needed multiply by 1,000 to convert mS to µS)		
(100014140 p.0/0111)			
Turbidity			
(NTUs)	12.5		
Reactive phosphorus			
(mgP/I)	60.03		
Photos of monitoring site taken upstream, across stream and downstream?			
These photos, with a heading to identify the sitecode, can be sent as an MMS to 0418145818 or emailed to			
deirdre.murphy@ccma.vic.gov.au.			
Additional observations eg what birds, plants, frogs are present?			
- Water ribbon			
-Azoola on Water surface			
-Azorla on Water surface, -Magpies, wattle birds, gallah's, haraceets, black wattles			
Record amount of litter		Record amount of illegal dumping	
Rating 1 to 5		Rating 1 to 5	
1		Do you need to take a photo and report to EPA?	