

Waterwatch Data Record Sheet

Monitor
P. Synne



Date and time: 18/08/17 - 10:30	Site Code: CO-BAR 089
Waterway and location: RIVER RESERVE, FANSTOCK, Cyril Synott Dr.	
Site Risk Assessment completed - yes / no	
Are there any incidents or near misses to report? - (if yes, please let Deirdre or Warren know) NO	

Parameter	Results
pH (pH units)	7.0
Electrical conductivity (record as $\mu\text{S}/\text{cm}$)	1,714 $\mu\text{S}/\text{cm}$ <small>(Write units displayed on meter. If needed multiply by 1,000 to convert mS to μS)</small>
Turbidity (NTUs)	30
Reactive phosphorus (mgP/l)	- 0.045

Photos of monitoring site taken upstream, across stream and downstream? These photos, with a heading to identify the sitecode, can be sent as an MMS to 0418145818 or emailed to deirdre.murphy@ccma.vic.gov.au .	
Additional observations eg what birds, plants, frogs are present? WATTLE BIRD, BRACKEN, REEDS → SITE IN GOOD CONDITION	
Record amount of litter Rating 1 to 5 2	Record amount of illegal dumping Rating 1 to 5 1 2 <i>Do you need to take a photo and report to EPA?</i>