## West Gippsland Waterwatch Volunteer Water Quality Monitoring Data Sheet

Site Details		Test Details		RECEIVED			
Site Code: HAZ 017		Date: 15	JULY 2010	16 JUL 2010			
Site Name: Hazel Creek @		Time:	Date: 15 JULY 2010 Time: 11.15 PAM PM				
Site Grid Reference Easting:		Person(s) Conducting the Survey / Test: JAVID STEELE					
Northing:		Name of Monito	Name of Monitoring Group: Warragul District Landcare Group				
Test Results			Weather Conditions at T	ime of Sampling			
Air Temperature	10.9	°C	Sunny	☐ Cloudy			
Water Temperature	9.3	°C	Overcast	☐ Raining			
рН	5.1		□ Windy				
Electrical Conductivity	200	□µS □mS					
Reactive Phosphorus	0.045	mg/L P	Last Rainfall				
Turbidity	9	N.T.U.	☐ More than a week ago	☐ During the last week			
			During the last 24 hours	☐ Raining Now			
	eries yet to		Amount of rain:	mm			
2 2							
			Water Flow				
Deepest Part of Stream (estimate only)			☐ Not flowing	Slow			
☑ Up to 50cm □	Up to 1m	Jp to 2m	☐ Fast	Rapid			
☐ Up to 5m ☐ Over 5m ☐ Unknown			☐ Temporary	☐ Permanent			
Average width of stream:	cm						
			Water Appearance				
Drains			Clear	Muddy			
Drain Flow: ☐ Drain flowing ☐ Drain not flowing			Milky	☐ Foamy / Frothy			
Description of drain water: Colour:			☐ Stained Green	☐ Stained Brown			
Odour:			☐ Smelly	Scummy			
			Oily	Other:			
Any Comments for Y	our Facilitator?						
			Litter Pollutants (tick type found)				
			☐ Paper	Plastic			
7			☐ Bottles	Cans			
			☐ Packets	☐ Polystyrene			
			☐ Car bodies	Petrol / diesel			
			☐ Clothing	☐ Waxed cardboard			
			☐ Other				

Your Meter - Pre Calibration Reading			Your Meter - Post Calibration Reading				
EC Meter	13	(00	3	EC Meter	14	10	
pH Meter in 7.01	7.4	pH Meter in 4.01	4.6	pH Meter in 7.01	7.0	pH Meter in 4.01	3.7