

West Gippsland Waterwatch Volunteer Water Quality Monitoring Data Sheet

Site Details: Site Code: HAZ 017, Site Name: Hazel CK at Ascott St, Site Grid Reference Easting: 406187, Northing: 5776729

Test Details: Date: 15 Nov 2010, Time: 11:20 AM, Person(s) Conducting the Survey / Test: DAVID STEELE, Name of Monitoring Group: WARRAGUL LANDCARE

Table with 2 main columns: Your Meter - Reading Before Calibration (when in CAL Mode) and Your Meter - Reading Post Calibration (after pressing the ENT button). Includes EC Meter and pH Meter in 7.01 readings.

Water Condition (Circle): Steady Flow (circled), Rising, Peak, Falling, Stagnant (pools), Dry (no water)

Test Results table: Air Temperature 16.1, Water Temperature 17.7, pH 5.9, Electrical Conductivity 180, Reactive Phosphorus 0.045, Turbidity 7, Dissolved Oxygen: —

Any Comments for Your Facilitator?: RECEIVED stamp dated 16 NOV 2010, BY: _____

Weather Conditions at Time of Sampling: Sunny, Overcast, Windy, Cloudy (checked), Raining

Water Appearance: Clear (checked), Milky, Stained Green, Smelly, Oily, Muddy, Foamy / Frothy, Stained Brown, Scummy, Other:

Last Rainfall: More than a week ago, During the last week (checked), Raining Now, Amount of rain: 10 mm

Drains: Drain Flow: Drain flowing, Drain not flowing (checked)