

West Gippsland Waterwatch Volunteer Water Quality Monitoring Data Sheet

| Site Details | |
|------------------------------|-----------------------|
| Site Code: | HAZ 017 |
| Site Name: | Hazel CK at Ascott St |
| Site Grid Reference Easting: | 406187 |
| Northing: | 5776729 |

| Test Details | RECEIVED |
|---|---|
| Date: | 15 JUNE 2010 |
| Time: | 1:00 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM |
| Person(s) Conducting the Survey / Test: | DAVID STEELE |
| Name of Monitoring Group: | Warragul Landcare |

| Your Meter - Reading Before Calibration (when in CAL Mode) | | | | Your Meter - Reading Post Calibration (after pressing the ENT button) | | | |
|---|------|------------------|-----|--|------|------------------|-----|
| EC Meter | 1450 | | | EC Meter | 1350 | | |
| pH Meter in 7.01 | 7.7 | pH Meter in 4.01 | 3.9 | pH Meter in 7.01 | 2.0 | pH Meter in 4.01 | 4.7 |

| Water Condition (Circle) | | | | | |
|--|------------------------------|----------------------------|-------------------------------|---|---|
| <input checked="" type="radio"/> Steady Flow | <input type="radio"/> Rising | <input type="radio"/> Peak | <input type="radio"/> Falling | <input type="radio"/> Stagnant (pools) | <input type="radio"/> Dry (no water) |

| Test Results | | |
|-------------------------|------|--|
| Air Temperature | 10.5 | °C |
| Water Temperature | 9.9 | °C |
| pH | 5.3 | |
| Electrical Conductivity | 230 | <input type="checkbox"/> µS <input type="checkbox"/> mS |
| Reactive Phosphorus | 0.01 | mg/L P |
| Turbidity | 6 | N.T.U. |
| Dissolved Oxygen: | — | <input type="checkbox"/> mg/L <input type="checkbox"/> % |
| | | |
| | | |

| Any Comments for Your Facilitator? |
|------------------------------------|
| |

| Weather Conditions at Time of Sampling | |
|---|----------------------------------|
| <input checked="" type="checkbox"/> Sunny | <input type="checkbox"/> Cloudy |
| <input type="checkbox"/> Overcast | <input type="checkbox"/> Raining |
| <input type="checkbox"/> Windy | |

| Water Appearance | |
|---|---|
| <input checked="" type="checkbox"/> Clear | <input type="checkbox"/> Muddy |
| <input type="checkbox"/> Milky | <input type="checkbox"/> Foamy / Frothy |
| <input type="checkbox"/> Stained Green | <input type="checkbox"/> Stained Brown |
| <input type="checkbox"/> Smelly | <input type="checkbox"/> Scummy |
| <input type="checkbox"/> Oily | <input type="checkbox"/> Other: |

| Last Rainfall | |
|---|--|
| <input type="checkbox"/> More than a week ago | <input checked="" type="checkbox"/> During the last week |
| <input type="checkbox"/> During the last 24 hours | <input type="checkbox"/> Raining Now |
| Amount of rain: | 15 mm |

| Drains | | |
|-------------|--|---|
| Drain Flow: | <input type="checkbox"/> Drain flowing | <input checked="" type="checkbox"/> Drain not flowing |