

# West Gippsland Waterwatch Volunteer Water Quality Monitoring Data Sheet

Site Details	
Site Code: TYR090	
Site Name: Tyers River @ Wilrilda Park	
Site Grid Reference Easting:	
Northing:	

Test Details	
Date: 26 JULY 2010	26 JUL 2010
Time: 1015 <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM	BY:
Person(s) Conducting the Survey / Test: Peter Bray Leanne Stubbs	
Name of Monitoring Group: Friends of Tyers Park	

Your Meter - Reading Before Calibration (when in CAL Mode)		Your Meter - Reading Post Calibration (after pressing the ENT button)	
EC Meter	<del>1400</del> 1360	EC Meter	
pH Meter in 7.01	7.9	pH Meter in 4.01	4.5

Water Condition (Circle)					
Steady Flow	Rising	Peak	Falling	Stagnant (pools)	Dry (no water)

Test Results		
Air Temperature	10.6	°C
Water Temperature	8.2	°C
pH	6.8	
Electrical Conductivity	130	<input checked="" type="checkbox"/> µS <input type="checkbox"/> mS
Reactive Phosphorus	0.015	mg/L P
Turbidity	15	N.T.U.
Dissolved Oxygen:		<input type="checkbox"/> mg/L <input type="checkbox"/> %

Any Comments for Your Facilitator?

Weather Conditions at Time of Sampling	
<input type="checkbox"/> Sunny	<input type="checkbox"/> Cloudy
<input checked="" type="checkbox"/> Overcast	<input type="checkbox"/> Raining
<input type="checkbox"/> Windy	

Water Appearance	
<input checked="" type="checkbox"/> Clear	<input type="checkbox"/> Muddy
<input type="checkbox"/> Milky	<input type="checkbox"/> Foamy / Frothy
<input type="checkbox"/> Stained Green	<input type="checkbox"/> Stained Brown
<input type="checkbox"/> Smelly	<input type="checkbox"/> Scummy
<input type="checkbox"/> Oily	<input type="checkbox"/> Other:

Last Rainfall	
<input type="checkbox"/> More than a week ago	<input checked="" type="checkbox"/> During the last week
<input type="checkbox"/> During the last 24 hours	<input type="checkbox"/> Raining Now
Amount of rain:	mm

Drains	
Drain Flow:	<input checked="" type="checkbox"/> Drain flowing <input type="checkbox"/> Drain not flowing