

17 MAR 2015

West Gippsland Waterwatch Volunteer Water Quality Monitoring Data Sheet

Site Details	
Site Code:	HAZ 017
Site Name:	Hazelck @ Ascott St
Site Grid Reference	Easting: 406187 Northing: 5776729

Test Details	
Date:	16 MARCH 2015
Time:	9.10 <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM
Person(s) Conducting the Survey / Test:	DAVID STEELE
Name of Monitoring Group:	WARRAGUL LANDCARE

Your Meter - Reading Before Calibration (when in CAL Mode)				Your Meter - Reading Post Calibration (after pressing the ENT button)			
EC Meter	1330			EC Meter	1410		
pH Meter in 7.01	7.0	pH Meter in 4.01	4.1	pH Meter in 7.01	7.0	pH Meter in 4.01	4.0

Water Condition (Circle)					
<u>Steady Flow</u>	Rising	Peak	Falling	Stagnant (pools)	Dry (no water)

Test Results		
Air Temperature	14.9	°C
Water Temperature	15.6	°C
pH	6.4	
Electrical Conductivity	230	<input type="checkbox"/> µS <input type="checkbox"/> mS
Reactive Phosphorus	0.015	mg/L P
Turbidity	7	N.T.U.
Dissolved Oxygen:		<input type="checkbox"/> mg/L <input type="checkbox"/> %

Any Comments for Your Facilitator?

Weather Conditions at Time of Sampling	
<input checked="" type="checkbox"/> Sunny	<input type="checkbox"/> Cloudy
<input type="checkbox"/> Overcast	<input type="checkbox"/> Raining
<input type="checkbox"/> Windy	

Water Appearance	
<input checked="" type="checkbox"/> Clear	<input type="checkbox"/> Muddy
<input type="checkbox"/> Milky	<input type="checkbox"/> Foamy / Frothy
<input type="checkbox"/> Stained Green	<input type="checkbox"/> Stained Brown
<input type="checkbox"/> Smelly	<input type="checkbox"/> Scummy
<input type="checkbox"/> Oily	<input type="checkbox"/> Other:

Last Rainfall	
<input type="checkbox"/> More than a week ago	<input checked="" type="checkbox"/> During the last week month
<input type="checkbox"/> During the last 24 hours	<input type="checkbox"/> Raining Now
Amount of rain:	40 mm

Drains		
Drain Flow:	<input type="checkbox"/> Drain flowing	<input checked="" type="checkbox"/> Drain not flowing