RECEIVED
15 OCT 2014
BY:

West Gippsland Waterwatch Volunteer Water Quality Monitoring Data Sheet

Site Details

Site Code: HAZ017
Site Name: Hazel CK at ASCOTT ST
Site Grid Reference Easting: 406187
Northing: 5776729

Test Details

Date: 14 Oct. 14
Time: 2.45 ☐ AM ☑ PM
Person(s) Conducting the Survey / Test: DAVID STEELE
Name of Monitoring Group: WARRAGUL LANDCARE

Your Meter - Reading Before Calibration (when in CAL Mode)				Your Meter - Reading Post Calibration (after pressing the ENT button)			
EC Meter	1390			EC Meter	1410		
pH Meter in 7.01	7.8	pH Meter in 4.01	4.1	pH Meter in 7.01	7.0	pH Meter in 4.01	4.0

Water Condition (Circle)

Steady Flow	Rising	Peak	Falling	Stagnant (pools)	Dry (no water)

Test Results

Air Temperature	17	°C
Water Temperature	14.9	°C
pH	5.4	
Electrical Conductivity	180	☐ µS ☐ mS
Reactive Phosphorus	0.015	mg/L P
Turbidity	9	N.T.U.
Dissolved Oxygen:		☐ mg/L ☐ %

Any Comments for Your Facilitator?

Weather Conditions at Time of Sampling

☑ Sunny ☐ Cloudy
☐ Overcast ☐ Raining
☐ Windy

Water Appearance

☑ Clear ☐ Muddy
☐ Milky ☐ Foamy / Frothy
☐ Stained Green ☐ Stained Brown
☐ Smelly ☐ Scummy
☐ Oily ☐ Other:

Last Rainfall

☐ More than a week ago ☐ During the last week
☑ During the last 24 hours ☐ Raining Now
Amount of rain: 57 mm (month)

Drains

Drain Flow: ☐ Drain flowing ☑ Drain not flowing

Post: West Gippsland Waterwatch
Reply Paid 1374 Traralgon 3844 or Fax: 51757899