West Gipps	sland Waterw	atch V	olunte	er '	Water Qua	lity Mon	itoring De	ita Shpet VEL	
Site Details			Test Details 27 NOV 2014					27 NOV 2014	
Site Code: Huk - 00/			Date:	Date: (8 - 1( - / CL					
Site Name: STORH	WATER IN		Time:	1	100 1	AM □	PIVI	0	
Site Grid Reference Easting: Person(s				) Co	nducting the Sur	vey/Test	beti-	e Cury,	
Northing: Name of N				Mon	Monitoring Group: HEY FIELD WETTAN				
Your Meter - Reading Before Calibration (when in CAL Mode)					Your Meter - Reading Post Calibration (after pressing the ENT button)				
EC Meter	,69 (1-)				EC Meter 1410				
pH Meter in 7.01 7.6	pH Meter in 4.01	4	6		pH Meter in 7.01	7-1	pH Meter in 4.01	41	
Test Results					Any Comments for Your Facilitator?				
Air Temperature	18	°C							
Water Temperature	19.1	°C							
рН	7.5								
Electrical Conductivity	130	Ψµs	□mS						
Reactive Phosphorus	0.11	mg/L P							
Turbidity	65	N.T.U.							
Depth	30 Gm								
Water Condition	at Time of Sa	ampling	9					Ç.A	
☐ Flood/overbank ☐ Dry					Weather Conditions at Time of Sampling				
☐ Bankfull	Bankfull Pools				Sunny		☐ Cld	oudy	
☐ High ☐ Stagnant					☐ Overcast		☐ Ra	ining	
Medium Permanent				☐ Windy					
Low									
					Last Rainfall				
			185		☐ More than	a week ago	Duri	ng the last week	
Water Appearance					☐ During the	e last 24 hours	s ☐ Rair	ning Now	
Clear				Amount of rain: 40 mm					
☐ Milky	Milky Foamy / Frothy								
☐ Stained Green	☐ Stained Green ☐ Stained Brown							eum ris	
☐ Smelly ☐ Scummy				Drains					
□ Oily	Dily Cther			Drain Flow	: Drain	n flowing	☐ Drain not flowing		

Oily

Other:

Drain Flow: