West Gipps	sland Waterw	atch Vo	luntee	Water Qualit	y Monitoring D	ata Sheet	
Site Details			Test Details			RECEIVE	
Site Code: TWV 545			Date: 2/9/2012			1 6 OCT 2012	
				2:10pm -AM	1 💢 PM	DV.	
Site Name: M055VDle Park Tortorn River Site Grid Reference Easting:			Person(s) Conducting the Survey / Test: Jem Milkins				
Northing: Name of I			Name of Mo	onitoring Group:			
Your Meter - Reading Before Calibration				Your Meter - Reading Post Calibration			
(when in CAL Mode)				(after pressing the ENT button)			
EC Meter pH Meter in	pH Meter in				er in pH Meter in		
7.01	4.01			7.01	4.01		
Test Results				Any Comments for Your Facilitator?			
Air Temperature	18.8	°C		Very	wet, lots slying as	s of	
Water Temperature	9.8	°C		water	s lying as	ound the	
рН	~			near	by Place	delains	
Electrical Conductivity	290	Ď(µS □] mS			•	
Reactive Phosphorus 6.03 mg/L P							
Turbidity	82	N.T.U.				3	
Depth		_	1				
Water Condition at Time of Sampling							
☐ Flood/overbank	☐ Dry			Weather Conditions at Time of Sampling			
☐ Bankfull	Pools			Sunny		loudy	
☐ High ☐ Stagnant			Overcast	☐ F	aining		
☐ Medium ☐ Permanent			□ Windy	_			
Low							
				Last Rainfa	all		
	э			☐ More than a v	veek ago 🔲 Du	ring the last week	
Water Appearance				☐ During the last 24 hours ☐ Raining Now			
☐ Clear	☐ Clear ☐ Muddy			Amount of rain: mm			
☐ Milky ☐ Foamy / Frothy			, -				
☐ Stained Green ☐ Stained Brown							
Smelly	☐ Smelly ☐ Scummy			Drains			
Oily	☐ Other:			Drain Flow:	☐ Drain flowing	☐ Drain not flowing	

Post: West Gippsland Waterwatch Reply Paid 1374 Traralgon 3844 or Fax: 51757899