West Gipps	land Waterwa	atch Voluntee	r Water Quality Mon	
Site Details  Site Code: LAT 021  Site Name: Latvobe 20 Scamos B. Time: 11  Site Grid Reference Easting: Person(s) 0			N-2011	
Water Condition (Circle)				
Steady Flow	Rising	Peak	Falling	Stagnant Dry (pools) (no water)
Test Results  Air Temperature  Water Temperature  pH  Electrical Conductivity  Reactive Phosphorus	7.5.	°C °C □ µS □ mS mg/L P		r Your Facilitator?
Turbidity Dissolved Oxygen:	J L	N.T.U.		
Weather Conditio	ns at Time of	Sampling	Water Appeara	nce
☐ Sunny ☐ Cloudy			☐ Clear	Muddy
☐ Overcast ☐ Raining		☐ Milky	► Foamy / Frothy	
□ Windy			☐ Stained Green	☐ Stained Brown
			☐ Smelly	☐ Scummy
Last Rainfall			Oily	☐ Other:
☐ More than a week ago ☐ During the last week			Li Ony	ц outer.
☐ During the last 24 hours ☐ Raining Now			Drains	

Post: West Gippsland Waterwatch Reply Paid 1374 Traralgon 3844 or Fax: 51757899

Drain Flow:

☐ Drain not flowing

☐ Drain flowing

mm

Amount of rain: