West Gippsland Waterwatch Volunteer Water Quality Monitoring Data Sheet Site Details Test Details Site Code: LAT 021 Date: 11-1-2011 site Name: UR Scarres Bridge 13 JAN 2011 Time: 6.15 \square AM Site Grid Reference Easting: Person(s) Conducting the Survey / Test: Northing: Name of Monitoring Group: Your Meter - Reading Before Calibration Your Meter - Reading Post Calibration (when in CAL Mode) (after pressing the ENT button) EC Meter **EC Meter** PH Meter in pH Meter in pH Meter in pH Meter in 4.01 4.01 Water Condition (Circle) Steady Flow Rising Stagnant Peak Dry Falling (pools) (no water) Test Results Any Comments for Your Facilitator? Air Temperature °C MOZZIES numerods Water Temperature ٥С рΗ Electrical Dµs □ms Conductivity Reactive Phosphorus mg/LP Turbidity N.T.U. Dissolved Oxygen: ☐ mg/L ☐ % Box with house hold Rutsbish Smells like something dead Weather Conditions at Time of Sampling loudy Raining

☐ Sunny Overcast Windy

| Last Rainfall | |
|--------------------------|--|
| ☐ More than a week ago | ☐ During the last week |
| During the last 24 hours | ☐ Raining Now |
| Amount of rain: | mmi |
| | The state of the s |

| ☐ Clear | Muddy |
|-----------------|-----------------|
| Milky | Foamy / Frothy |
| ☐ Stained Green | ☐ Stained Brown |
| ☐ Smelly | ☐ Scummy |
| Oily | Other: |

| Drains | | |
|-------------|-----------------|-------------------|
| Drain Flow: | ☐ Drain flowing | Drain not flowing |

(Briggling this morning

Post: West Gippsland Waterwatch Reply Paid 1374 Traralgon 3844 or Fax: 51757899