West Gipps	sland Waterw	ratch Volun	teer Water Quality Monitoring Data Sheet
Site Details			t Details
Site Code: HWC-002			21-4-15 28 APR 2013
			1300 DAM DAMY:
Site Grid Reference Easting: Person			n(s) Conducting the Survey / Test:
Northing: Name			e of Monitoring Group: Mexicol Western
Your Meter - Readi	ng Before Calil	oration	Your Meter - Reading Post Calibration
(when in CAL Mode)			(after pressing the ENT button)
EC Meter	`	~	EC Meter
pH Meter in 7.01	pH Meter in 4.01		pH Meter in 7 - C pH Meter in 4.01 4.01
Test Results			Any Comments for Your Facilitator?
Air Temperature	17.4	°C	
Water Temperature	18-6	℃	
pH	6.7		
Electrical Conductivity	550	ITÚS □mS	
Reactive Phosphorus	033	mg/L P	
Turbidity	21	N.T.U.	
Depth	25 cm		
Water Condition			
☐ Flood/overbank	☐ Dry		Weather Conditions at Time of Sampling
☐ Bankfull ☐ Pools			Cloudy
☐ High ☐ Stagnant		ent	Overcast Raining
Medium	☐ Perma	nent	☐ Windy
Low			
			Last Rainfall
			More than a week ago During the last week
Water Appearance			☐ During the last 24 hours ☐ Raining Now
Clear		5	Amount of rain: / mm
Milky	☐ Foamy /	Frothy	
☐ Stained Green	☐ Stained	Brown	
☐ Smelly ☐ Scummy			Drains

Other:

Drain Flow:

☐ Drain not flowing

☐ Drain flowing