West Gippsland Waterwatch Volunteer Water Quality Monitoring Data Sheet

	Test Details					
Site Code: MOR040		02.2011	RECEIVE			
Rd Bridge	Time:	-2 MAR 2011				
Site Grid Reference Easting: Northing:		Person(s) Conducting the Survey / Test: Joelle Champert				
		Name of Monitoring Group: YYSLCG				
		Weather Conditions at	Time of Sampling			
21.6	°C	Sunny	Cloudy			
22	°C	☐ Overcast	Raining			
7.2		Windy				
300	⊠µS □mS					
	mg/L P	Last Rainfall				
35	N.T.U.	☐ More than a week ago	☐ During the last week			
31000		During the last 24 hours	☐ Raining Now			
		Amount of rain:	⊘ mm			
		Water Flow				
Deepest Part of Stream (estimate only) ☐ Up to 50cm ☐ Up to 1m ☐ Up to 2m		☐ Not flowing	Slow			
		Fast	Rapid			
☐ Up to 5m ☐ Over 5m ☐ Unknown			☐ Permanent			
cm						
		Water Appearance				
Drains						
Drain Flow: ☐ Drain flowing ☐ Drain not flowing			☐ Foamy / Frothy			
Description of drain water: Colour:			☐ Stained Brown			
Odour:		☐ Smelly	☐ Scummy			
		Oily	Other:			
acilitator?						
		Litter Pollutants (tick type found)				
		☐ Paper	☐ Plastic			
		☐ Bottles	☐ Cans			
		☐ Packets	☐ Polystyrene			
		☐ Packets ☐ Car bodies	☐ Polystyrene ☐ Petrol / diesel			
	7.2 300 0.14 35 dimate only) n	Date: (9. Time: Person(s) Cond Name of Monito 21.6 °C 22 °C 3.00 ⊠ µS □ mS 0.14 mg/L P 3.5 N.T.U. Climate only) n □ Up to 2m n □ Unknown cm □ Drain not flowing Colour: Odour:	Date:			

Your Meter - Pre Calibration Reading			Your Meter - Post Calibration Reading				
EC Meter	1440			EC Meter	1410		
pH Meter in 7.01 test	7.5	pH Meter in 4.01 test	4.5	pH Meter in 7.01 test	7.0	pH Meter in 4.01 test	4.0

Post: PO BOX 1374 Traralgon 3844 or Fax: 51757899