West Gippsland Waterwatch Volunteer Water Quality Monitoring Data Sheet

Site Details		Test D	etails				
Site Code: MOR040		Date:	12/03/2010				
Site Name: Morwell River @ Nuta	alls Rd Bridge	Time:	L+ DAM DPI				
Site Grid Reference Easting:		Person(s) Conducting the Survey / Test: Joelle Champert					
Northing:		Name of Monitoring Group: YYSLCG					
Test Results			Weather Conditions	at Time of Sampling			
Air Temperature	29.2	°C	Sunny	☐ Cloudy			
Water Temperature	19.4	°C	☐ Overcast	Raining			
рН	6.8		. Windy				
Electrical Conductivity	350	⊠ μS □ ms	5				
Reactive Phosphorus	.03	mg/L P	Last Rainfall				
Turbidity	5	N.T.U.	☐ More than a week ago	☑ During the last week			
			☐ During the last 24 hours	☐ Raining Now			
			Amount of rain:	70 mm			
**	To Assert William LANGER	- 12. To 12. To 2017/2/demak.	Water Flow				
Deepest Part of Stream (estimate only)			☐ Not flowing	Ślow			
☐ Up to 50cm ☐ Up to 1m ☐ Up to 2m			Fast	Rapid			
☐ Up to 5m ☐ Over	5m 🔲	Unknown	Temporary	Permanent			
Average width of stream:	cm		**				
,	в		Water Appearance				
Drains			☑ Clear	☐ Muddy			
Drain Flow: ☐ Drain flowing ☐ Drain not flowing			☐ Milky	☐ Foamy / Frothy			
Description of drain water: Colour:			☐ Stained Green	☐ Stained Brown			
Odour:			☐ Smelly	☐ Scummy			
			□ Oily	Other:			
Any Comments for Your	Facilitator?						
			Litter Pollutants (tic	k type found)			
			☐ Paper	☐ Plastic			
			☐ Bottles	☐ Cans			
			☐ Packets	Polystyrene			
			☐ Car bodies	☐ Petrol / diesel			
			☐ Clothing	☐ Waxed cardboard			
			☐ Other				

Your Meter - Pre Calibration Reading			Your Meter	Your Meter - Post Calibration Reading			
EC Meter	1220		EC Meter	155	0		
pH Meter in 7.01 test	7.5	pH Meter in 4.01 test	pH Meter in 7.01 test	7.0	pH Meter in 4.01 test	4.0	