

West Gippsland Waterwatch Volunteer Water Quality Monitoring Data Sheet

Site Details					
Site Code: HAZ015	Site Name: H	Site Name: Hazel Ck / King st WARRAGUL			
Site Grid Reference Easting: 4052		298	Northing: 577471	Northing: 5774710	
Test Details			1. (SAR)	<i>-</i> ,	
Date: 12-1-2022 Person(s) Conducting the Test: 2. DICK					
Date: 12-1-2022 Person(s) Conducting the Test: 2. Dick Time:					
Preparation					
* <u>pHmeter</u> calibrated: (Y) N (circle) <u>EC meter</u> conditioned: (Y) N (circle)					
				^ '	
Took Boowles			Calibrati	ed. (1)/14 (circle)	
Test Results	Air Town 1 2 7 7		- 7 7 Fire 6		
Water Temp.: 22, 2°C	Air Temp.: 22.5	C pri valu	e: 7·2 . Elec. 0	Conduct.: 295 µS	
Reactive Phosphorus:	<u> つ・0</u> 30 mg/L (P)	Turbidity: 20	NTU	
Weather Conditions at Tim	e of Sampling (please tick	k)			
Sunny	☑ Cloudy	☐ Overcast	☐ Raining	Windy Windy	
Last Rainfall (please tick)			Al		
☐ More than a week ago	During the last week	☐ During the last 24	hrs Raining Now	Amount of rain: / 7.5 mm	
Water Flow: (please tick) ☐ Bank-full - High flow within channel capacity, and in-stream habitats connected ☐ High - Less than bank-full, and in-stream habitats connected ☐ Medium - Flow is normal / typical average flow ☐ Low - Minimum flow in channel/ continuous flow in some part of channel (in-stream habitat connected) ☐ Dry - No continuous flow in channel and no pools ☐ Pools - No continuous flow in channel and intermittent pools (in-stream habitats not connected)					
	2				
Water Appearance (please t		5 0	—	- /	
☑ Clear ☐ Muddy	☐ Scummy ☐ Milky	☐ Smelly ☐ Oily	☐ Foamy / Frothy☐ Stained Green	Stained Brown	
				Other:	
Stream Depth and Width (p. Depth: ☑ 0-50cm	lease ticκ) Other:				
Width: ☑ 2-5m	Other:				
Circumstantial Hazards and Additional Risks					
Hazard:		Risk:			
Risk Control Measures:					
		¥			
Comment: Key in data, and store the form in our local files in case of later query. (No requirement to post to Traralgon.)					

Print Date 5 January 2022



www.wacma.vic.gov.au