

Waterwatch Results: Friends of Dandenong Valley Parklands Dandenong Creek and Blind Creek

Tests completed by: Christine Dix, Edie Buckley, Zoë Laxton, Bryan Loft, Simon Lam, Simon Ling

Test Completed Date: 27/5/22	Dandenong Creek Bridge site (DDN 050)	Blind Creek Jells Lake (DBC 250) ME DJE 200
Time:	10.16	10.35
Ammonium mg/l	0.0	0.04
D.O. (Dissolved oxygen concentration)	6.4 61.39%	5.6 53.9%
Electrical Conductivity	540	240
pH (Acidity/alkalinity)	7.1	7.4
Reactive Phosphate (Nutrient levels)	0.03	0.07
Air Temperature	16.1	15.4 15.9
Water Temperature	13.4	14.3 13.6
Turbidity	10	0

Site Descriptions	Dandenong Creek Bridge site (DDN 050)	Blind Creek Jells Lake (DBC 250)
Weather (Sunny, cloudy, overcast, raining, windy)	overcast	overcast
Rainfall (More than a week, during last week, last 24 hours, raining now)	not 24hrs	last 24hrs
Amount of rainfall	5mm	5mm
Water flow (Flood, Medium, Low)	Med	Medium
Water appearance (Clear, muddy, milky, other)	Clear	muddy clear
Stream depth (0- 50cm, 51 - 100cm, 1 - 2m, >2m)	0-50	51-100 0-50
Stream width (3 - 5m, >5m)	>5m	3-5 N/A
Litter/pollutants	plastic bottles 5 plastic ball coffee cup. plastic	none