Water Quality Data - Collection Form

Site Code	GB-SEVO 44	**Date/Time**	3/5/25 5:30
Calibration EC	Yes ☑ No ☐	**Calibration pH**	Yes ☑ No ☐
Electrical Conductivity	178 µS/cm	**pH**	6.9
Turbidity	13 NTU	**Water Temperature**	15.3 °C
Dissolved Oxygen	N/A mg/L	**Air Temperature**	19 °C
Dissolved Oxygen	N/A %		

Weather Conditions

Sunny	☑	Overcast	☐	Raining	☐	Windy	☐
Cloudy	☐	Other:					

Rainfall

More than a week ago	☑	During the last week	☐	During the last 24 hours	☐	Raining now	☐

Amount of Rain

_____ mm

Water Flow

- ☐ **FLOOD / OVERBANK** - flow is high and water level has exceeded bank capacity and is connecting with floodplain
- ☐ **BANKFULL** - High flow within channel capacity and in-stream habitats connected
- ☐ **HIGH** - Less than bankfull and in-stream habitats connected
- ☑ **MEDIUM** - Flow is normal/typical average flow
- ☐ **LOW** - Minimum flow in channel / continuous flow in some part of channel (in-stream habitats connected)
- ☐ **DRY** - No continuous flw in channel and no pools
- ☐ **POOLS** - No continuous flow n channel and intermittent pools (in-stream habitats not connected)
- ☐ **STAGNANT** - No continuous flow in channel but channel continuous (in-stream habitats connected)
- ☐ **PERMANENT** - Wetlands and lakes

Water Appearance

Clear	☐	Smelly	☐	Muddy	☑	Oily	☐
Stained Green	☐	Stained Brown	☐	Milky	☐		
Foamy/Frothy	☐	Scummy	☐	Other:			

Stream Depth

0-50cm	☐	51-99cm	☐	1m - 2m	☑	>2m	☐

Stream Width

< 2m	☐	2-5m	☐	> 5m	☑	

Drains

Water Flowing from drains: Yes ☐   No ☑

Colour:

Odour:

Cicumstantial hazard and additional risks

Hazard

Risk

Control Measures   N/A

Litter Pollutants

Bottles/Cans	☐	Oil	☐	Polystyrene	☐	Petrol / Diesel	☐
Car Bodies	☐	Clothing	☐	Plastic	☐		
Wax Cardboards	☐	Packets	☐	Paper	☐		