

Waterwatch

Water Quality Data Form

Site: Old pipe bridge - Plenty River

Date: 7.06.26

Monitoring group: PRRP

Time: 10:15

Persons monitoring: Seema, Priya, Damoh,
Tahnee, River

Circumstantial Hazard or Additional Risks

Hazard: wet, slippery highwater

Risk: slips, trips, falls, drowning

Risk Control Measures: don't fall

Safety Check

Has anything changed at your site recently?

Are there extreme weather conditions?

Any animals or insects nearby that pose a risk?



Parameter		Reading	
Ammonium		0.00	mg / L
Dissolved Oxygen	(Use data portal to auto calculate % saturation)	9	mg / L
Water Temperature		12.6	° C
Air Temperature		18.4	° C
pH	☒ Calibrated	7.4	Unit
Electroconductivity	☒ Calibrated	416	µS / cm
Phosphate	(for colorimeter use conversion on data portal, or divide by 0.326 to calculate PO4-P mg/L)	0.005	mg / L
Turbidity		35	NTU
Nitrate		0	mg / L

Comments:

Ammonium was originally 0.07. on repeat it was 0.



melbournewater.com.au/waterwatch



Waterwatch

Observations

Weather

Condition:

☐ Sunny
☐ Raining

☒ Cloudy
☐ Windy

☐ Overcast

Rainfall

Last Rainfall:

☐ More than a week ago

☐ During the last week

☒ During the last 24 hours

☐ Raining now

Amount of rain (mm):

54.6 (weekly)

Water Flow

Flow Indicator (ML/Day):

95

Estimate of flow:

☐ Flood / overbank

☐ Bankfull

☒ High

☒ Medium

☐ Low

Water Appearance

☐ Clear

☐ Scummy

☐ Smelly

☐ Foamy / frothy

☒ Stained brown

☐ Muddy

☐ Milky

☐ Oily

☐ Stained green

Other:

Stream Depth:

☐ 0-50cm 0.25

☐ 51cm - 99cm

☐ 1m - 2m

☐ Other

Stream Width:

☐ <2m

☐ 2 - 5m

☒ >5m

☐ Other

Drains

Is water flowing from drain? ☒

Colour

Odour

Litter Pollutants

☐ Bottles

☐ Car bodies

☐ Oil

☐ Paper

☐ Plastic

☐ Waxed cardboard

☐ Cans

☐ Clothing

☐ Packets

☐ Petrol / diesel

☐ Polystyrene

Other:

Juice bottle



melbournewater.com.au/waterwatch



Melbourne Water

Enhancing Life and Liveability