

Waterwatch

Water Quality Data Form

Site: Old pipe bridge

Date: 5 July 2026

Monitoring group: PRRP

Time: 9:15am

Persons monitoring: Seema, Prina, Alice, Carley,
Damon, Violet,

Circumstantial Hazard or Additional Risks

Hazard: slope to river slippery,

Risk: Trip/fall

Risk Control Measures: Hold handrail

Safety Check

Has anything changed at your site recently?

Are there extreme weather conditions?

Any animals or insects nearby that pose a risk?



Parameter		Reading	
Ammonium		not recording	mg / L
Dissolved Oxygen	(Use data portal to auto calculate % saturation)	8	mg / L
Water Temperature		10.9	° C
Air Temperature		11.6	° C
pH	☒ Calibrated	6.5, 7.1, 7.2	Unit
Electroconductivity	☒ Calibrated	455	µS / cm
Phosphate	(for colorimeter use conversion on data portal, or divide by 0.326 to calculate PO4-P mg/L)	No recording	mg / L
Turbidity		100	NTU
Nitrate		0	mg / L

Comments: phosphate & ammonium was hard to read due to and
due to high turbidity & rainfall.

Waterwatch

Observations

Weather

Condition: ☐ Sunny ☐ Cloudy ☒ Overcast
☐ Raining ☐ Windy

Rainfall

Last Rainfall: ☐ More than a week ago ☐ During the last week **21.4 mm**
☐ During the last 24 hours ☐ Raining now
Amount of rain (mm): **1 mm**

Water Flow

Flow Indicator (ML/Day): **173.8 ML/Day**

Estimate of flow: ☐ Flood / overbank ☐ Bankfull ☒ High
☐ Medium ☐ Low

Water Appearance

☐ Clear ☒ Stained brown ☐ Stained green
☐ Scummy ☒ Muddy
☐ Smelly ☐ Milky
☐ Foamy / frothy ☐ Oily

Other:

Stream Depth: ☒ 0-50cm ☐ 51cm - 99cm ☐ 1m - 2m ☐ Other
0.315m

Stream Width: ☒ <2m ☒ 2 - 5m ☒ >5m ☐ Other

Drains

Is water flowing from drain? ☐ **NIA**

Colour

Odour

Litter Pollutants

☐ Bottles ☐ Plastic ☐ Packets
☐ Car bodies ☐ Waxed cardboard ☐ Petrol / diesel
☐ Oil ☐ Cans ☐ Polystyrene
☐ Paper ☐ Clothing

Other: