WATERWATCH Corangamite
Communities Caring For Catchments

Physical & Chemical Tests Record Sheet

(To be completed monthly)

Site Name: BG TREE WYE RIVER	Site Code: OSD
Name of Monitoring Group: WYE River Waterwatch	
Person(s) Conducting the test: Anne C, Erica, Juliette, Helen, Jan, Frank	
Date of test: 3/10/2026	Time of test: 10:51
Site Risk Assessment Completed: ☑ signature please: (see inside back cover flap) Please note any circumstantial hazards and additional risks (see below)	

Test	Result (units)		Comments
D.O.	9.4 mg/L	% sat.	
Water Temperature		12 °C	
Air Temperature		14 °C	
pH	Tick if meter has been calibrated to pH 7 ☑ & 10 pH ☐	6.8	
Salinity	Tick if meter has been calibrated to 2000 EC ☐	186 E.C.	
Reactive Phosphorus	0.01 mg/L P		
Turbidity	79.7 (N.T.U.) F.T.U.		High - due to rainfall

Weather conditions at the time of sampling:

☐ sunny ☐ cloudy ☐ overcast ☑ raining ☑ windy

Rainfall:

Last rainfall: ☐ More than week ago ☐ During the last week ☑ During the last 24 hours ☐ Raining now

Amount of rain _____ _____ _____

Water flow

Flow indicator _____ ML/day

Estimate of flow

☐ Not flowing ☐ Slow
☐ Moderate ☑ Rapid
☐ Temporary ☐ Permanent

Water appearance

☐ Clear ☐ Milky ☐ Foamy /frothy
☑ Muddy ☐ Smelly ☐ Stained green
☐ Scummy ☐ Oily ☐ Stained brown
☐ Other (description) _____

Stream depth and width

Depth indicator _____ metres ☐ 0 - 50 cm ☐ 51cm - 1m deep ☐ 1 to 2 metres
Average width of stream: _____ metres ☐ 2 to 5 metres ☑ >5 metres ☐ Unknown

Unknown

Drains

Water flowing from drain ☐
Color _____ Odour _____
No water flowing from drain ☐

Circumstantial hazard and additional risks

Hazard: Fast flowing water Risk: Falling
Risk Control Measures: Take care, Distance from bank

Litter pollutants: (Tick type found)

☐ paper ☐ bottles ☐ plastic ☐ clothing ☐ car bodies
☐ packets ☐ cans ☐ polystyrene ☐ oil ☐ petrol/diesel
☐ waxed cardboard ☐ other